Weathertzehlen Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization
Audit Name: MADISON

CLIENT INFORMATION

Client Name: Address:

Client ID: 16016SW-1001

AGENCY INFORMATION

Agency: SWHRA Agency Phone: (731) 989-5111

Address: 1574 White AVE Fax:
Henderson, TN Email Address:

Agency Contact: Oliver, Jerry Work Phone:

Cell Phone: Email Address: () (

Company Name & License Number: ______Contractor's Signature:

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-424-1507

Client Name: Client ID: Alt. Client ID: 16016SW-1001 Work Order (Bid Form)

Work Order Name:

Report Run On: 5/15/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 6

Measures

i	Measure 1 Infilti	ration Redctn			Component	's		ı	nspected
C	Comment								
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal old flu in living room and chimney, Seal crown molding and corners, Seal around All AC units	Each	1					
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal around breaker box and door jam to bathroom. Seal around tud and vanity	Each	1			d)		
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Seal ceiling to wall around chimney in itchen,Seal pipes under sin and pipes behind washer and dryer	Each	1					
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Seal cuiling abone washer, Seal floor to wall by water heater and old chimney. Seal baseboard in hall	Each	1					
8	Labor	Labor	Hour						
9	Construction Materials/Hardwar e	Caulk all windows and glaze as needed	Each	1					
10	Labor	Labor	Hour						

Report Run On: 5/15/2010

Page 2 of 6

Other Detail	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	·	,			7	·	
] []		
				Cut Tatale	***************************************		Sub Total:	
			weasur	e Sub Total:				
Field Notes:								
		,						
Measure 2 Attic	Ins. R-30			Componen	ts A1		:	Inspected
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	960					
2 Labor	Labor	Hour	960					
3 Construction Materials/Hardwar e	Install attic access cover	Each	200	Warman				
4 Labor	Labor	Hour						
Other Detail								
			J L	ا لــــــــــــــــــــــــــــــــــــ			Sub Total:	
			Measur	e Sub Total:		<u> </u>	Jan Total.	
Field Notes:								
]

Measure 3 DW	H Pipe Insulation			Componen	ts		I	nspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1				The state of the s	
2 Labor	Labor	Each	1					
Other Detail						n [
			Measur	e Sub Total:] :	Sub Total:	
Field Notes:								
								- 1
Measure 4 Wal	l Insulation			Componen			,	nspected
	l Insulation			Componen		2,E3,N1 2,W1,W	,	Inspected
Measure 4 Wal	Insulation			-	S1,S2		2	Inspected
Comment		Units		Estimated	S1,S2	2,W1,W	2 Actual	
Comment # Material / Labor	Description / Comment	<i>Units</i>	Qty	-	S1,S2		2	Inspected
Comment		<i>Units</i> SqFt		Estimated	S1,S2	2,W1,W	2 Actual	
Comment # Material / Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated	S1,S2	2,W1,W	2 Actual	
Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	Qty 1040	Estimated	S1,S2	2,W1,W	2 Actual	
Comment # Material / Labor 1 Insulation	Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	Qty 1040	Estimated	S1,S2	2,W1,W	2 Actual	
Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	Qty 1040	Estimated	S1,S2	2,W1,W	2 Actual	
Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt SqFt	Qty 1040	Estimated	S1,S2	Qty	2 Actual	
Comment # Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt SqFt	Qty 1040	Estimated Unit Cost	S1,S2	Qty	Actual Unit Cost	
Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt SqFt	Qty 1040	Estimated Unit Cost	S1,S2	Qty	Actual Unit Cost	
Comment # Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt SqFt	Qty 1040	Estimated Unit Cost	S1,S2	Qty	Actual Unit Cost	

N	leasure 5	DWH	Tank Insulation			Componen	ts		•	Inspected
C	omment									
						Estimated			Actual	
#	Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Hot Water Equipment		DHW Tank Insulation	Each	1					
2	Labor		Labor	Each	1					
0	ther Detail							,		
L										
					Measur	e Sub Total:] .	Sub Total:	
Γ	Field Notes:						3.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1			
L										
	leasure 6	Storn	n Windows		wanter	Componen	ts W1			Inspected
	leasure 6	Storn	n Windows	Annual (1974)		Componen	ts W1			Inspected
		Storm	า Windows			Componen Estimated			Actual	Inspected
Co			n Windows Description / Comment	Units	Qty	·		Qty		Inspected Total
#	omment	oor		<i>Units</i> Each		Estimated		Qty	Actual	
# 1	omment Material / Lab	oor	Description / Comment		Qty	Estimated		Qty	Actual	
# 1 2	omment Material / Lab Windows Labor	oor	Description / Comment Storm Window	Each	Qty 1	Estimated		Qty	Actual	
# 1 2	omment Material / Lab Windows	oor	Description / Comment Storm Window	Each	Qty 1	Estimated		Qty	Actual	
# 1 2	omment Material / Lab Windows Labor	oor	Description / Comment Storm Window	Each	Qty 1	Estimated		Qty	Actual	
# 1 2	omment Material / Lab Windows Labor	oor	Description / Comment Storm Window	Each Hour	Qty 1 8	Estimated			Actual	
# 1 2 0	omment Material / Lab Windows Labor ther Detail	oor	Description / Comment Storm Window	Each Hour	Qty 1 8	Estimated Unit Cost			Actual Unit Cost	
# 1 2 0	omment Material / Lab Windows Labor	oor	Description / Comment Storm Window	Each Hour	Qty 1 8	Estimated Unit Cost			Actual Unit Cost	
# 1 2 0	omment Material / Lab Windows Labor ther Detail	oor	Description / Comment Storm Window	Each Hour	Qty 1 8	Estimated Unit Cost			Actual Unit Cost	

Measure 7 Fix A	ny Other Heating Sys	tem Proble	m	Component	's		-	Inspected
Comment Remove heater	non-vented heaters ar	nd cap gas l	ine. P	lace new hea	ater in ha	ll by		
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Counter Flow Direct Vent 50-55 KBTU Propane Heater	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
]		i	Measur	e Sub Total:			Sub Total:	
Field Notes:						w-12	<u></u>	
								O Maria de la Carta de la Cart

1					-			
Measure 8 Pres Comment	sureRelief Piping Nee	ded		Component	's		į	Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Pressure relief piping	Each	1					
2 Labor	Labor	Hour	1					
Other Detail		1	***************************************					
		i	Measur	e Sub Total:		\$	Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	

Client Name:

Client ID:

Alt. Client ID: 16016SW-1001

Work Order (Bid Form)

Work Order Name Report Run On: 5/15/2010 DOE Weatherization Assistant Version 8.5.0 Page 6 of 6